

## **APPENDIX A - Investigation Participants**

### **Mine Safety and Health Administration**

Allyn C. Davis, Accident Investigation Coordinator, Coal Mine Safety and Health  
P. Michael Hall, Chief, Electrical Section  
William A. McGilton, Supervisory Coal Mine Safety and Health Inspector  
Ronald L. Sidwell, Coal Mine Safety and Health Inspector, (Electrical)  
Daniel L. Stout, Electrical Engineer  
Clete R. Stephan, Mining Engineer, Pittsburgh Safety and Health Technology Center  
Chris A. Weaver, Mining Engineer, Ventilation  
Joseph R. Yudas, Coal Mine Safety and Health Inspector

### **West Virginia Office of Miner's Health, Safety and Training**

John Larry, Assistant Inspector-At-Large  
Brian Mills, Inspector-At-Large  
Roger Powell, Inspector-At-Large

### **Consolidation Coal Company**

Charles E. Bane, Safety Supervisor  
Dave A. Clise, Mine Foreman  
John T. Higgins, Superintendent  
Jack A. Holt, Vice President Safety  
Richard Marlowe, Chief Inspector

### **United Mine Workers of America**

Mark Cochran, Mine Safety Committee Chairman  
Wayne Conaway, Miner's Representative  
Rich Eddy, District 31 President  
Dennis O'Dell, International Representative  
Terry Osborne, Regional Director  
Gary Trout, International Representative  
Roy Williams, Miner's Representative

## **APPENDIX B - Persons Interviewed**

John T. Higgins, Superintendent  
Dave A. Clise, Mine Foreman  
Mark Watkins, Assistant Superintendent  
Clarence Moore, Longwall Foreman (Afternoon Shift)  
Dave Frazier, Longwall Foreman (Day Shift)  
Mike Tatterson, Maintenance Foreman (Day Shift)  
Linz Booth, General Inside Labor (Day Shift)  
Larry Straight, General Inside Labor (Day Shift)  
Leo McIntosh, Mechanic (Day Shift)  
Walt Simatic, Shift Foreman (Afternoon Shift)  
Jeff Myers, Belt Foreman (Day Shift)  
Arthur Reeves, Shift Foreman (Midnight Shift)  
Steve Harris, Longwall Foreman (Midnight Shift)  
Jim Welch, Maintenance Foreman (Midnight Shift)  
Wyatt Bitteringer, Maintenance Foreman (Midnight Shift)  
Terry Osborne, Foreman (Midnight Shift)  
Roger Lee Sharp, Yard Foreman (Midnight Shift)  
Jim Ammons, Fireboss (Midnight Shift)  
Dave Wilson, Electrical Foreman (Day Shift)




## APPENDIX C – Dust Sample Analysis Results

Sample #	Location (refer to map on page 44)	Incombustible Content (%)	Coke Content	Sample Description	Date Collected
1	2D, C Entry, between crosscuts 11-12	Not Analyzed	X-Large	Band	01/08/2001
2	2D, B Entry, between crosscuts 11-12	Not Analyzed	X-Large	Band	01/08/2001
3	2D, C Entry, between crosscuts 2-3	Not Analyzed	X-Large	Band	01/08/2001
4	2D, B Entry, between crosscuts 2-3	Not Analyzed	X-Large	Band	01/08/2001
5	9-South, F Entry, between crosscuts 12-13	Not Analyzed	X-Large	Band	01/08/2001
6	9-South, E Entry, between crosscuts 12-13	Not Analyzed	Small	½ Floor & Left Rib	01/08/2001
7	9-South, D Entry, between crosscuts 13-14	Not Analyzed	Large	Floor & Ribs	01/08/2001
8	9-South, C Entry, between crosscuts 14-15	Not Analyzed	X-Large	Band	01/08/2001
9	9-South, B Entry, between crosscuts 14-15	Not Analyzed	X-Large	Band	01/08/2001
10	9-South, A Entry, between crosscuts 14-15	Not Analyzed	X-Large	Band	01/08/2001
11	9-South, F Entry, between crosscuts 20-21	Not Analyzed	Large	¾ Floor & Left Rib	01/08/2001
12	9-South, E Entry, between crosscuts 20-21	Not Analyzed	X-Large	Floor & Ribs	01/08/2001
13	9-South, D Entry, between crosscuts 20-21	Not Analyzed	X-Large	Band	01/08/2001
14	9-South, C Entry, between crosscuts 20-21	Not Analyzed	X-Large	Band	01/08/2001
15	9-South, B Entry, between crosscuts 20-21	Not Analyzed	X-Large	Band	01/08/2001
16	9-South, A Entry, between crosscuts 20-21	Not Analyzed	X-Large	Band	01/08/2001
17	9-South, A Entry, between crosscuts 23-24	Not Analyzed	X-Large	Band	01/09/2001
18	9-South, B Entry, between crosscuts 23-24	Not Analyzed	X-Large	Band	01/09/2001
19	9-South, C Entry, between crosscuts 23-24	Not Analyzed	X-Large	Band	01/09/2001
20	9-South, D Entry, between crosscuts 23-24	Not Analyzed	Small	Band	01/09/2001
21	9-South, E Entry, between crosscuts 23-24	Not Analyzed	Large	Floor & Ribs	01/09/2001
22	9-South, F Entry, between crosscuts 23-24	Not Analyzed	X-Large	Band	01/09/2001
23	9-South, G Entry, between crosscuts 22-23	Not Analyzed	X-Large	Band	01/09/2001
24	9-South, G Entry, between crosscuts 20-21	Not Analyzed	X-Large	Band	01/09/2001
25	9-South, H Entry, between crosscuts 20-21	Not Analyzed	X-Large	Band	01/09/2001
26	2D, A Entry, between crosscuts 2-3	Not Analyzed	Large	Band	01/09/2001
27	2D, A Entry, between crosscuts 11-12	Not Analyzed	Large	Band	01/09/2001
28	2D, D Entry, between crosscuts 11-12	Not Analyzed	X-Large	Band	01/09/2001
29	2D, D Entry, between crosscuts 2-3	Not Analyzed	Small	Floor	01/09/2001
30	9-South, G Entry, between crosscuts 12-13	Not Analyzed	Small	Band	01/09/2001
31	9-South, F Entry, between crosscuts 25-26	34.10	X-Large	Floor	01/23/2001
32	9-South, E Entry, between crosscuts 25-26	59.40	X-Large	Floor	01/23/2001
33	9-South, D Entry, between crosscuts 25-26	47.60	X-Large	Floor	01/23/2001
34	9-South, C Entry, between crosscuts 25-26	45.90	X-Large	Floor	01/23/2001
35	9-South, B Entry, between crosscuts 25-26	56.10	X-Large	Floor	01/23/2001
36	9-South, A Entry, between crosscuts 25-26	83.10	X-Large	Floor	01/23/2001
37	9-South, A Entry, between crosscuts 27-28	81.00	X-Large	Floor	01/23/2001
38	9-South, B Entry, between crosscuts 27-28	52.90	X-Large	Floor	01/23/2001
39	9-South, C Entry, between crosscuts 27-28	39.40	X-Large	Floor	01/23/2001
40	9-South, D Entry, between crosscuts 28-29	36.60	X-Large	Floor	01/23/2001
41	9-South, E Entry, between crosscuts 28-29	47.80	X-Large	Floor	01/23/2001
42	9-South, F Entry, between crosscuts 28-29	53.30	X-Large	Floor	01/23/2001
43	9-South, G Entry, between crosscuts 28-29	49.70	X-Large	Floor	01/23/2001
44	3D, B Entry, between crosscuts 2-3	20.20	X-Large	Floor	01/23/2001
45	3D, C Entry, between crosscuts 2-3	39.00	X-Large	Floor	01/23/2001
46	3D, A Entry, between crosscuts 2-3	53.60	X-Large	Floor	01/23/2001
47	3D, D Entry, between crosscuts 2-3	40.60	X-Large	Floor	01/23/2001
48	9-South, G Entry, between crosscuts 25-26	37.70	X-Large	Floor	01/23/2001

# APPENDIX C





## Dust Sample Locations


MSHA Report of Investigation  
 Loveridge No. 22 Mine Fire / Explosion




**Figure 1 - 2-Left Fire Area**


MSHA Report of Investigation  
Loveridge No. 22 Mine Fire / Explosion  
June 22, 1999

-  Roof Fall
-  Control Breached By Fire
-  Unexplored
-  Airflow Direction At Time of Fire















**Figure 5 (bottom left):** Mine rescue team members apply foam sealant to the St. Leo fan housing on June 22, 1999.

**Figure 6 (bottom right):** Damage to St. Leo fan and shaft after the explosion on June 26, 1999. The deflection of the top of the shaft partition is visible in this photograph.












**Figure 8 (top left):** Flooded elevator shaft bottom at the Sugar Run Portal.


**Figure 9: (bottom):** Main West conditions during the initial examinations.

**Figure 10 (top right):** August 8, 2000, air change to clear methane from the south side of Main West.










Note: Gas concentrations shown represent test results at time of initial exploration of each area. Ventilation was extended after exploring to Crosscut 52.

**Figure 12 - St. Leo Headings  
Exploration 8/30 - 9/1/2000**  
MSHA Report of Investigation  
Loveridge No. 22 Mine Fire / Explosion









## Junction of 9-South & St. Leo Headings

**Notes:** Nonpermissible photographic equipment was not used in this area until more permanent isolation controls were installed. As a result, Figures 14-17 were taken after rock dust was applied during the recovery operations.

Refer to [Figure 13](#) for the locations of images shown on this page.

**Figure 14 (top):** St. Leo Shaft bottom, showing concrete and steel rubble from the destroyed shaft partition. This material extended approximately 50 feet up into the shaft.



**Figure 15 (center left):** Power center in 9-South Crosscut 3. Note the concrete block from the adjacent stopping, which was blown into the power center by the explosive forces.

**Figure 16 (center right):** Trailer lifted off the floor and transported down the 9-South No. 3 entry during the explosion.



**Figure 17 (bottom):** Overcast in Crosscut 2 of the 1D entries. Debris was scattered in all directions from the belt entry on the lower side of the overcast.





## 8-North Roof Fall & 1D Seal

**Figure 18 (top):** A miner crawls across the top of the roof fall in the 8-North No.7 entry.

**Figures 19 & 20 (center):** Debris along the left side of the approach to the 8-North No. 7 entry roof fall illustrates the volume of material that was manually removed during the recovery efforts.

Location of Figures 18-20 shown on [Figure 1](#).




**Figure 21 (bottom):** The 1D seals were equipped with steel access panels that were bolted in place. These panels permitted mine rescue teams to clear methane accumulations from immediately inby the seals upon resuming recovery of the 1D and 2D entries.

Refer to [Figure 22](#) for the location of this seal.



# Figure 22 - 9-South Exploration Map

MSHA Report of Investigation  
Loveridge No. 22 Mine Fire / Explosion



Airflow direction, as of 12/11/2000.  
This flow pattern was extended to each fresh air base as the recovery proceeded.





**Figure 23 (top):** This vacuum breaker box was thrown by explosive forces from the crosscut, on the right side of this picture, and deposited on the track where it was hit by additional forces from an inby direction (photo taken while facing outby in the track entry).

**Figure 24 (center left):** The smaller temporary belt was rolled away from the track entry (photo looking outby).

**Figure 25 (center right):** Damage to belt structure at an overcast.



**Figure 26 (bottom left):** Destroyed fire fighting station.

**Figure 27 (bottom right):** Investigation team surveys damage to ventilation controls.

**Note:** Refer to [Figure 22](#) for locations of images shown on this page.





**Figure 28 (top):** A miner observes the rock dust pods located near Crosscut 21 in the 9-South track entry. The steel pod in the foreground was imploded, while that nearest the miner remained intact.



**Figure 29 (center left):** Outby end of Locomotive #55.


**Figure 30 (center right):** Inby end of Locomotive #55.



**Figure 31 (bottom):** Air compressor tank on a rock dusting machine, located at the end of the 9-South track entry.

**Note:** Refer to [Figure 22](#) for locations of images shown on this page.





**Note:** Refer to [Figure 22](#) for locations of images shown on this page.

**Figure 32 (top):** Head roller assembly that was being installed at the junction of the 3D and 9-South belt entries. The roof elevation in the adjacent 9-South belt entry is visible in the lower right corner of this image.


**Figure 33 (center left):** Inby end of Locomotive #1B.

**Figure 34 (center right):** View across the top of Locomotive #1B.



**Figures 35-36 (bottom):** Rust particles deposited on the mine floor. These particles dropped 6-7 feet from rusting roof bolt channels, forming detailed images of the channels on the floor throughout 9-South. This indicated that there was no natural ventilation in the submain after the explosion.








Figure 38 - 2D Section  
Exploration Map  
MSHA Report of Investigation  
Lovridge No. 22 Mine Fire / Explosion  
June 22, 1999





## 2D Section Damage


(images taken after area was rock dusted)

**Figure 39 (top):** Cable car blown into supply cars by forces from the adjacent belt entry to the right.

**Figure 40 (center left):** Damaged power car near the end of the track.

**Figure 41 (center right):** The track was displaced and rail was broken by forces from the adjacent belt entry.


**Figure 42 (bottom left):** Batteries blown off of scoop.



**Figure 43 (bottom right):** Damaged power car (same as Figure 40)

**Note:** [Figure 38](#) shows image locations.





**Figure 44 - Line Diagram of  
Primary Ventilation Splits**  
MSHA Report of Investigation  
Loveridge No. 22 Mine Fire / Explosion  
June 22, 1999





## 2-Left Fire Area

**Figure 45 (top):** Burned roof coal and cribbing adjacent to a roof fall near the fire origin.

**Figure 46 (center):** Roof fall covering a scoop that was loaded with the last section of the belt take-up following cutting operations.


**Figure 47 (bottom left):** Power centers located in the 8-North entries, just outby the fire origin.

**Figure 48 (bottom right):** Soot deposits a stopping in the return entry immediately downwind of the fire origin.

**Note:** Refer to [Figure 1](#) for image locations.







Detail: June 22, 1999

Figure 49 - Miracle Run Fan  
Pressure Recording Chart  
MSHA Report of Investigation  
Loveridge No. 22 Mine Fire / Explosion  
June 22, 1999

Note: Fan chart recording period:  
12:03 p.m., June 15, 1999  
to  
8:40 p.m., June 22, 1999




Figure 50 - 9-South  
Direction of Forces  
MSHA Report of Investigation  
Loveridge No. 22 Mine Fire / Explosion

